## Approved For Release 2003/09/30 : CIA-RDP69B00041R000400050011-8


25X1

Copy 6 of 11

10 August 1967

### MEMORANDUM FOR THE RECORD

SUBJECT: Critique for OXCART Mission Number BX6709



### 2. Mission Data:

- a. Mission Number: BX6709
- b. Date Flown: 19 July 1967
- c. Area of Operation: North Vietnam
- d. Mission Success: Successful

#### 25X1A

- e. Pilot's Name:
- f. Aircraft Number: 131
- g. Primary or Spare Flown: Primary
- h. Takeoff Time: Planned: 19/0200Z
  - Actual: 19/0256Z
- i. Landing Time: Planned: 19/0704Z
  - Actual: 19/0754Z
- j. Time Enroute: Planned: 5:04
  - Actual: 4:58

### 25X1A

- k. Departure Base: Kadena
- 1. Landing Base: Kadena
- m. Equipment:
- 3. Operations: Due to loss of 28V ground power at H-2, which required run-up to be re-started, A-12 takeoff was delayed and second window timing was used.

downgrading and		1	2.5
CROUP 1 Excluded from automatic downgrading and			
	•	•	

declassification Approved For Release 2003/09/30 : CIA-RDP69B00041R000400050011-8

25X1

25X1

## Approved For Release 2003/09/30 : CIA-RDP69B00041R000400050011-8

Page	2			

25X1

25X1

- a. Route (INS plot vs. planned). All flight lines were flown within INS spec error. An overshoot of approximately 9 NM occurred on turn after first flight line, undershoot of approximately 4 NM occurred on turn after second flight line.
  - (1) INS Terminal Error: 11.0 NM
  - (2) INS Spec Error: 13.8 NM
  - b. Mission Generation & Operational Support: Satisfactory.
- 4. Weather:
- a. Forecast vs. Actual: As briefed, Category II on all photographic flight lines.
  - b. Weather Scout Reporting: Satisfactory.
- 5. Intelligence:
  - a. Target Coverage:
    - (1) 14 of 16 programmed targets were covered.
    - (2) 21 of 48 North Vietnam COMOR targets were covered.
    - (3) 5 of 9 priority SSM targets in North Vietnam were covered.
  - (4) 166 SAM sites were identified (12 sites were occupied and 4 new sites identified).
  - b. Quality of Take:
  - (1) Resolution: One to one and one-half feet at NADIR throughout the mission.
  - (2) Camera Operation: Satisfactory, imagery was reported as excellent by NPIC.

Approved For Release 2003/09/30 : CIA-RDP69B00041R000400050011-8

25X1

## Approved For Release 2003/09/30 : CIA-RDP69B00041R000400050011-8

d. Significant Findings:  (1) With only 12 of 166 SAM sites occupied, there is some doubt that there are 25-30 firing battallions as estimated.  (2) Figure eight, driver training course, similar to those seen in China, noted for the first time in North Vietnam situated near Lao Cai.  e. Take Movement:  (1) Camera: Satisfactory.  f.  6. Materiel:  a. Aircraft General:  (1) Fuel did not transfer properly during flight due to number six fuel pump failure.  (2) Manual disconnect was required on third air refueling due to defective holding coil.  (3) Malfunctions which occurred during flight did not limit mission performance.  b. Aircraft Systems: All systems performed satisfactorily.		
(1) With only 12 of 166 SAM sites occupied, there is some doubt that there are 25-30 firing battallions as estimated.  (2) Figure eight, driver training course, similar to those seen in China, noted for the first time in North Vietnam situated near Lao Cai.  e. Take Movement:  (1) Camera: Satisfactory.  6. Materiel:  a. Aircraft General:  (1) Fuel did not transfer properly during flight due to number six fuel pump failure.  (2) Manual disconnect was required on third air refueling due to defective holding coil.  (3) Malfunctions which occurred during flight did not limit mission performance.		Page 3
(1) With only 12 of 166 SAM sites occupied, there is some doubt that there are 25-30 firing battallions as estimated.  (2) Figure eight, driver training course, similar to those seen in China, noted for the first time in North Vietnam situated near Lao Cai.  e. Take Movement:  (1) Camera: Satisfactory.  6. Materiel:  a. Aircraft General:  (1) Fuel did not transfer properly during flight due to number six fuel pump failure.  (2) Manual disconnect was required on third air refueling due to defective holding coil.  (3) Malfunctions which occurred during flight did not limit mission performance.		
(1) With only 12 of 166 SAM sites occupied, there is some doubt that there are 25-30 firing battallions as estimated.  (2) Figure eight, driver training course, similar to those seen in China, noted for the first time in North Vietnam situated near Lao Cai.  e. Take Movement:  (1) Camera: Satisfactory.  6. Materiel:  a. Aircraft General:  (1) Fuel did not transfer properly during flight due to number six fuel pump failure.  (2) Manual disconnect was required on third air refueling due to defective holding coil.  (3) Malfunctions which occurred during flight did not limit mission performance.		
(1) With only 12 of 166 SAM sites occupied, there is some doubt that there are 25-30 firing battallions as estimated.  (2) Figure eight, driver training course, similar to those seen in China, noted for the first time in North Vietnam situated near Lao Cai.  e. Take Movement:  (1) Camera: Satisfactory.  6. Materiel:  a. Aircraft General:  (1) Fuel did not transfer properly during flight due to number six fuel pump failure.  (2) Manual disconnect was required on third air refueling due to defective holding coil.  (3) Malfunctions which occurred during flight did not limit mission performance.		
doubt that there are 25-30 firing battallions as estimated.  (2) Figure eight, driver training course, similar to those seen in China, noted for the first time in North Vietnam situated near Lao Cai.  e. Take Movement:  (1) Camera: Satisfactory.  f.  6. Materiel:  a. Aircraft General:  (1) Fuel did not transfer properly during flight due to number six fuel pump failure.  (2) Manual disconnect was required on third air refueling due to defective holding coil.  (3) Malfunctions which occurred during flight did not limit mission performance.		d. Significant Findings:
seen in China, noted for the first time in North Vietnam situated near Lao Cai.  e. Take Movement:  (1) Camera: Satisfactory.  6. Materiel:  a. Aircraft General:  (1) Fuel did not transfer properly during flight due to number six fuel pump failure.  (2) Manual disconnect was required on third air refueling due to defective holding coil.  (3) Malfunctions which occurred during flight did not limit mission performance.		
(1) Camera: Satisfactory.  f.  6. Materiel:  a. Aircraft General:  (1) Fuel did not transfer properly during flight due to number six fuel pump failure.  (2) Manual disconnect was required on third air refueling due to defective holding coil.  (3) Malfunctions which occurred during flight did not limit mission performance.		seen in China, noted for the first time in North Vietnam situated
f.  6. Materiel:  a. Aircraft General:  (1) Fuel did not transfer properly during flight due to number six fuel pump failure.  (2) Manual disconnect was required on third air refueling due to defective holding coil.  (3) Malfunctions which occurred during flight did not limit mission performance.		e. Take Movement:
<ul> <li>6. Materiel: <ul> <li>a. Aircraft General:</li> <li>(1) Fuel did not transfer properly during flight due to number six fuel pump failure.</li> <li>(2) Manual disconnect was required on third air refueling due to defective holding coil.</li> <li>(3) Malfunctions which occurred during flight did not limit mission performance.</li> </ul> </li> </ul>		(1) Camera: Satisfactory.
<ul> <li>6. Materiel: <ul> <li>a. Aircraft General:</li> <li>(1) Fuel did not transfer properly during flight due to number six fuel pump failure.</li> <li>(2) Manual disconnect was required on third air refueling due to defective holding coil.</li> <li>(3) Malfunctions which occurred during flight did not limit mission performance.</li> </ul> </li> </ul>		
<ul> <li>6. Materiel: <ul> <li>a. Aircraft General:</li> <li>(1) Fuel did not transfer properly during flight due to number six fuel pump failure.</li> <li>(2) Manual disconnect was required on third air refueling due to defective holding coil.</li> <li>(3) Malfunctions which occurred during flight did not limit mission performance.</li> </ul> </li> </ul>		
<ul> <li>a. Aircraft General: <ul> <li>(1) Fuel did not transfer properly during flight due to number six fuel pump failure.</li> <li>(2) Manual disconnect was required on third air refueling due to defective holding coil.</li> <li>(3) Malfunctions which occurred during flight did not limit mission performance.</li> </ul> </li> </ul>		;
<ul> <li>(1) Fuel did not transfer properly during flight due to number six fuel pump failure.</li> <li>(2) Manual disconnect was required on third air refueling due to defective holding coil.</li> <li>(3) Malfunctions which occurred during flight did not limit mission performance.</li> </ul>	6.	Materiel:
six fuel pump failure.  (2) Manual disconnect was required on third air refueling due to defective holding coil.  (3) Malfunctions which occurred during flight did not limit mission performance.		a. Aircraft General:
to defective holding coil.  (3) Malfunctions which occurred during flight did not limit mission performance.		
mission performance.		* *
b. Aircraft Systems: All systems performed satisfactorily.		·
		b. Aircraft Systems: All systems performed satisfactorily.
		,
· ·		

	TOP SECRET	_
Approved For Release 20	03/09/30 : CIA-RDP69B0	     0041R000400050011-8

25X1

25X1

c. AGE: INS rectifier test cart had intermittent power loss due to open circuit in "C" pin in "cart to aircraft plug." Loss of power at H-2 required INS run-up to be re-started, delaying takeoff.

- 7. Communications:
  - a. Message Traffic: Satisfactory.

25X1A

- 8. Significant Actions Taken: None required.
- 9. Outstanding Actions Required:
  - a. Ascertain if mission was hand flown (OXC/Ops).
- b. Determine correlation between camera used and quality of take. (R&D)
- c. Request future "Operational Sortie Reports" submitted by include time or points along route during which autopilot operated in other than auto/auto.

Note: Subsequent report confirmed aircraft was operated in auto/auto throughout mission except manual pitch used due Mach hold oscillation.

WILLIAM E. SHELTON

Colonel, USAF

Deputy for Operations, OSA

.

25X1A

25X1A

Approved For Release 2003/09/30 : CIA-RDP69B00041R000400050011-8

25X1

25X1

TOP SECRET

# Approved For Release 2008/09/30 : CIA-RDP69B00041R000400050011-8

2	5	Χ	1
_	v	/\	- 1

25X1

Page 5

25X1A

OXC/O/OSA

Distribution:

- #1 D/SA
- #2 D/O/OSA
- #3 D/M/OSA
- #4 D/R&D/OSA
- #5 OXC/O/OSA
- #6 Intel/O/OSA
- #7 Wea/O/OSA
- #8 Commo/O/OSA
- #9 ADP/O/OSA
- #10 RB/OSA
- #11 Chrono

25X1

TOP SECRET